








i

+

Output 40 °C

	205	323
↓ 40 %	140 A 100 %	200 A 100 %
↓ 35 %	130 A 100 %	190 A 100 %



userdoc.kemppi.com

Mounting instructions

W025412 R00